

**NECA 305-2018 Standard for Fire Alarm Job Practices**

**Errata**

Section	Clause	Page No.	Correction
4	4.3(p)	13	The relative humidity should be less than <del>93%</del> 85% at 32°C (90°F)